

Delayed Connection to Door Stations When Using IPW-1VC or IPW-10VC

Problem

The IPW-1VC and IPW-10VC are adaptors that allow IX Series door stations to be connected using existing two-conductor cabling. This allows for a PoE connection without having to run additional wire. In some instances, there may be a noticeable delay between when the call is answered on the master station and when the call connects.


Explanation

The adaptor has a lower bandwidth than standard Cat-5e/6 cable. When the door station is connected to a VMS, the secondary video stream can impact the speed of the main connection.

Solution

Reduce the bit rate in the video settings to improve the connection speed.

In IX Support Tool, navigate to **Network Settings**, Video.



Scroll right to ONVIF Transmit Channel. For the affected door station, use the drop-down menu to change the Bit rate to 1024 kbps. Click **Update**.

Network Settings							
Video							
Video Station							
ONVIF Transmit Channel							
Second Video Encoder	Video Codec	Resolution	Frame Rate (fps)	Select Profile [H.264 / AVC]	I-picture interval [H.264/AVC]	Bit rate (kbps) [H.264 / AVC]	
Enable	H.264/AVC	1280x720(HD)	10	Main		10	1024
Enable	H.264/AVC	1280x720(HD)	10	Main		10	32
Enable	H.264/AVC	1280x720(HD)	10	Main		10	64
Enable	H.264/AVC	1280x720(HD)	10	Main		10	128
Enable	H.264/AVC	1280x720(HD)	10	Main		10	256
Enable	H.264/AVC	320x240(QVGA)	15	Main		15	384
							512
							768
							1024
							2048
							4096
							8192

Once all settings are configured, select **File (F)** from the top bar and select Upload Settings to Station. Click **Select** to check all of the stations, then click on **Settings**. Click **OK** on the confirmation pop-up to begin the upload.