


WIRING DIAGRAM

5 LEF-3's and 3 LE-A's



Remove all E/- jumpers
Shielded wire is recommended.