


DB system with DA-4DS door



L and L terminals on the door station provide 15vac for door release strike.

RESISTANCE OF 20 OHMS IS *CRITICAL*. Simple strikes (i.e, Trine 001) will NOT work, as they have too high of a current draw, due to too low of a resistance. Most manufacturers make a lower draw / higher resistance replacement (Trine 1001).